

# SERVICE BULLETIN

**Date:** February 11, 2015  
**Update Number:** S2015-03  
**Subject:** Lower Gear Reducer Leaking Oil  
**Product Affected:** CSW24V

Recently, we received a small number of field reports stating the lower gear reducer on the model CSW24V leaked a minimal amount of oil. We have worked with our supplier to identify the cause of the leak and have determined that a low number of reducers were filled with an excess amount of oil.

When this condition occurs and the operator is run continuously, a small amount of oil may leak out through the vent plug. If you encounter a CSW24V with a lower gear reducer that is leaking oil, a replacement Gear Reducer Service Kit (K32-35814), filled to specification, is available for immediate shipment. For more information on this issue, please contact Technical Support at 800.528.2806.

## GEAR REDUCER

