

PRODUCT BULLETIN

Date: August 23, 2013
Update Number: P2013-13
Subject: New Revision 4.3 Plug-In Loop Detector Firmware
Products Affected: Model LOOPDETLM



Due to popular customer demand, we have changed the functionality of our plug-in loop detector.

Enhanced Functionality

The new revision 4.3 firmware will hold the detect state as long as a vehicle is present on the loop in lieu of tracking out over time. As soon as the vehicle leaves the loop, the loop detector will release from the detect state.

Loop detectors with the new firmware started shipping August 19th and can be identified by a revision 4.3 label located on the side of the detector and packaging. If you have a question about the new revision 4.3 loop detector firmware, please call Technical Support at 800.528.6563.

To place an order, contact your LiftMaster Sales Representative or call Customer Service at 800.282.6225 or visit Dealer.LiftMaster.com.