

# Product Bulletin

**Date:** July 30, 2022  
**Update Number:** P2022-23  
**Subject:** Discontinuance of LiftMaster® Industrial Slide Gate Operators  
**Products Affected:** All SL585 and SL595 Series Gate Operators

With the launch of the IHSL24ULMC and the upcoming launch of INSL24ULMC, LiftMaster will discontinue the legacy industrial gate operator product listed below.

The new line of Industrial Slide Gate Operators is designed for retrofit to the existing SL585 and SL595 series to reduce installation time and site modifications. Please refer to the MRIN

<https://www.liftmaster.com/riser-for-industrial-operators/p/MRIN> on LiftMaster.com for more details.

Models Being Discontinued	Recommended Replacement	Date when Discontinued
SL585101ULMC	INSL24ULMC	September 23, 2022
SL585501ULMC	INSL24ULMC	September 23, 2022
SL585103ULMC	INSL24ULMC	September 23, 2022
SL585151ULMC	INSL24ULMC	September 23, 2022
SL585503ULMC	INSL24ULMC	September 23, 2022
SL585105ULMC	INSL24ULMC	September 23, 2022
SL595101ULMC	IHSL24ULMC	August 26, 2022
SL595103ULMC	IHSL24ULMC	August 26, 2022
SL595151ULMC	IHSL24ULMC	August 26, 2022
SL595203ULMC	IHSL24ULMC	August 26, 2022
SL595105ULMC	IHSL24ULMC	August 26, 2022
SL595204ULMC	IHSL24ULMC	August 26, 2022

For more information regarding this update, please contact your LiftMaster Sales Representative or call our Technical Support Center at **800.528.2806**. Please visit **Partner.LiftMaster.com** for a complete listing of our Product and Service Bulletins.